

FIG.1




FIG.2




FIG.3




FIG.4

1




FIG.5





FIG.6






FIG.8

	h = 1.00			
	X1	Y1	X2	Y2
1	100,	100,	1100,	1100,
2	1200,	100,	2200,	1100,
3	100,	3100,	1100,	4100,
4	1200,	3100,	2200,	4100,

FIG.9




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14




FIG.15

	X 1	Y1	X2	Y2	h
[a]	X1a,	Y1a,	X2a,	Y2a,	ha
[b]	X1b,	Y1b,	X2b,	Y2b,	hb
[c]	X1c,	Y1c,	X2c,	Y2c,	hc
[d]	X1d,	Y1d,	X2d,	Y2d,	hd

FIG.16